



Large particles do not enter the packing material.
They have less volume to cross and exit sooner.

Small particles can enter the packing material.
This slows them down and they exit later.